S VIET NAM: On 5 October 1865, an Air Force memberr was killed in an F-100 aircraft while on a pre-strike mission over South Viet Nam. Aircraft was observed to go in on ordnance run, make contact with the ground and explode. Specific cause of accident is unknown however ground fire from unfriendly forces was in area. Remains not recovered.

• - 1st Lt John C. HAUSCHILLDT, 63878A, Chicago,. Illinois P